Field survey - corridor service bay

Survey FS-27-07 | September 7, 2026, 07:40 | Eden Moss, site surveyor

R03 | Record date: 2026-09-07 | Units: mm unless noted

1. Survey basis

WC-27 / SA-27 location, Level 2 east corridor. Dimensions in millimetres. Datum C0 is the exposed planar front face of the fixed cladding carriers. Measurements taken before veneer panels and cassette installation. Opposite wall finish is complete.

2. Observations

Perpendicular distance from C0 to the opposite finished wall: 1295 at three points across the intended tray-withdrawal zone; lowest observed distance recorded. No other projections were visible within that zone on this visit. Carrier support opening: 738 horizontal x 920 vertical, measured square at its front edge. This support opening is not the cladding frame-mounting cutout or the frame throat.

3. Unmeasured interface

Final projection P from C0 to finished cladding face was not established: rail packers and cassette backing have not been selected. No installed panel or tray was available for a withdrawal check. Field report records geometry only and does not approve component sizing or release fabrication.